

## ENERGY EFFICIENCY CERTIFICATE

Builder, Permit Holder or Registered Design Professional

Print Name: Quality One Contracting

Signature: 

Property Address: 230 Rollins Mill Rd.  
Holly Springs, NC 27540

Date: 1/7/20

Insulation Rating - List the value covering largest area to all that apply	R-Value
Ceiling/Roof:	R- <u>38</u>
Wall:	R- <u>15</u>
Floor:	R- <u>19</u>
Closed Crawl Space Wall:	R- <u>10</u>
Closed Crawl Space Floor:	R- <u>N/A</u>
Slab:	R- <u>N/A</u>
Basement Wall:	R- <u>N/A</u>

**Fenestration:**

U-Factor	
Solar Heat Gain Coefficient(SHGC)	

**Building Air Leakage**

Visually inspected according to N1102.4.2.1 OR

Building Air Leakage Test Results  
(Sec. N1102.4.2.2)  
ACH50 [Target: 5.0] or  
CFM50/SFSA [Target: 0.30]

Name of Tester/Company: **EcoStructure Energy Consulting, LLC**

Date: 1/7/20 Phone: **919.452.5829**

**Ducts:**

Insulation:	R- <u>8</u>
Total Duct Leakage Test Result (Sect. N1103.3.3) Circle one: <u>Total duct leakage test</u> (CFM25 Total/100SF) (Target: 5) or Duct Leakage to the outside test (CFM25 Total/100SF) (Target: 4)	<u>3.3</u>

Name of Tester/Company: **EcoStructure Energy Consulting, LLC**

Date: 1/7/20 Phone: **919.452.5829**

Certificate to be displayed permanently.