

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

10/1/2019

SUBJECT: **SFD1904-0028**

SINGLE FAMILY DWELLING

To: Sadler Construction

Here are the results of all Inspections located at 142 BRAE DR:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Scott Guy

Result: Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Scott Guy

Result: Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Scott Guy

Result: Remarks: Notes:





108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Scott Guy

Result: Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 6/19/2019
Completed Date/Time: 6/19/2019
Inspector: Scott Guy
Result: APPROVED

Remarks: Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 6/19/2019
Completed Date/Time: 6/19/2019
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 142 Brae Dr

Lillington, NC 27546

**Lot 15

Inspection Type: FOUNDATION
Scheduled Date/Time: 7/15/2019 Any
Completed Date/Time: 7/15/2019
Inspector: Ray Holder
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/12/2019 1:24 PM Sadler Construction

Contact Name: Sadler Construction

Site Address: 142 BRAE DR Phone: 9199093906

1110116. 5155055500

e-Mail: jason@SadlerConstructionNC.com

Inspector SBL changed the inspection assignment from SBL to RLH



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE

Scheduled Date/Time: 7/17/2019 Any Completed Date/Time: 7/17/2019 Inspector: Ray Holder Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/14/2019 4:30 PM Sadler Construction

We have a foundation inspection scheduled for 7/15/19. Would you be able to do the T-Pole

inspection on the same date? Thank you and God Bless.

Contact Name: Sadler Construction

Site Address: 142 BRAE DR Phone: 9199093906

e-Mail: jason@SadlerConstructionNC.com

Inspector TSG changed the inspection assignment from TSG to RLH

No premise number in permit

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: 7/31/2019
Completed Date/Time: 7/31/2019
Inspector: Jennifer Brock
Result: APPROVED

Remarks: Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 9/18/2019
Completed Date/Time: 9/18/2019
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks:

Notes: Inspector TSG changed the inspection assignment from TSG to SPG

Missing front porch post and attachments. Missing toilet flanges. Missing Ivl paperwork.

Missing nut and washer in garage wing wall.



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 9/25/2019 Any
Completed Date/Time: 9/25/2019
Inspector: Scott Guy
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 9/24/2019 8:48 AM Sadler Construction

Contact Name: Sadler Construction

Site Address: 142 BRAE DR

Phone: 9199093906

e-Mail: jason@SadlerConstructionNC.com

Inspector TSG changed the inspection assignment from TSG to SPG Inspector SPG changed the inspection assignment from SPG to TSG

Inspection Type: INSULATION
Scheduled Date/Time: 9/30/2019
Completed Date/Time: 9/30/2019
Inspector: Scott Guy
Result: APPROVED

Remarks: Notes:

Inspection Type: TAX INSPECTION

Scheduled Date/Time: 10/2/2019

Completed Date/Time:

Inspector: Kyle Holder

Result: Remarks: Notes:

