Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: Date Evaluated: 5/28/19
Proposed Facility: 3 BDRMS Design Flow (.1949): 360 gpd Property Size:
Location of Site: Property Recorded:
Water Supply: ☒ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☐ Auger Boring ☒ Pit ☐ Cut
Type of Wastewater: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	LS 7-10	0-14	G L	VFR MS/NP					
		14-42	SBK C	F, S/P					PS .25
		42+	~50%PM						
2		0-16	G L	VFR MS/NP					
		16-46	SBK C	F/FR S/P					PS .25
3		0-17	G L	VFR MS/NP					
		17-44	SBK C	FR S/P					PS .25

Description	Initial System	Repair System
Available Space (.1945)	✓	
System Type(s)	3BR 10 RGD	
Site LTAR	.25	.25

Other Factors (.1946):
Site Classification (.1948): PS
Evaluated By: CT
Others Present: OC