

108 EAST FRONT STREET

LILLINGTON,NC 27546 Phone:

Fax:

9/17/2019

SUBJECT: **SFD1905-0008**

SINGLE FAMILY DWELLING

To: On Top Building Company LLC

Here are the results of all Inspections located at 108 WYNNRIDGE DR:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: WATERPROOFING

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:





108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result: Remarks: Notes:

Inspection Type: FINAL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Deen Taylor

Result:

Remarks: eTRAKiT Inspection Request

Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 6/19/2019 Any
Completed Date/Time: 6/19/2019
Inspector: Deen Taylor
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 6/17/2019 1:33 PM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: FOUNDATION Scheduled Date/Time: 7/5/2019 Any Completed Date/Time: 7/5/2019 Inspector: Ray Holder Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 6/28/2019 2:59 PM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 7/22/2019 Any
Completed Date/Time: 7/22/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/16/2019 9:10 AM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: ROUGH IN
Scheduled Date/Time: 8/2/2019 Any
Completed Date/Time: 8/2/2019
Inspector: Deen Taylor
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/31/2019 2:07 PM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 8/8/2019 Any Completed Date/Time: 8/8/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/5/2019 11:39 AM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Harnett C O U N T Y NORTH CAROLINA

Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 8/8/2019 Any
Completed Date/Time: 8/8/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/5/2019 10:53 AM On Top Building Company LLC

Premise Number is 64984223

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: INSULATION
Scheduled Date/Time: 8/8/2019 Any
Completed Date/Time: 8/8/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/5/2019 7:37 AM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 8/8/2019 Completed Date/Time: 8/8/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 8/8/2019 Completed Date/Time: 8/8/2019

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: Notes:



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: 8/22/2019 Completed Date/Time: 8/22/2019

Inspector: Slade Burton Lawson III

Result: CANCELLED

Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 9/4/2019 Any Completed Date/Time: 9/4/2019 Inspector: Deen Taylor Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 9/3/2019 8:09 AM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 9/11/2019
Completed Date/Time: 9/11/2019
Inspector: James Manhart
Result: APPROVED

Remarks: Notes:

Inspection Type: FINAL**

Scheduled Date/Time: 9/13/2019 Any Completed Date/Time: 9/13/2019 Inspector: Ray Holder Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 9/11/2019 1:46 PM On Top Building Company LLC

Contact Name: On Top Building Company LLC

Site Address: 108 WYNNRIDGE DR

Phone: 9192011133

e-Mail: ontopbuildingcompany@gmail.com



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: 1) need weather stripping on attic access door. 2) seal around range wire. 3) caulk crack

Scheduled Date/Time: between drywall and tub in master. 4) caulk toilets at floor.

Completed Date/Time

Inspection Type: ADDRESS
Scheduled Date/Time: 9/16/2019
Completed Date/Time: 9/16/2019
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 108 WYNNRIDGE DR ANGIER 27501.

Inspection Type: TAX INSPECTION

Scheduled Date/Time: 9/16/2019
Completed Date/Time: 9/16/2019 AM
Inspector: Terry Wade
Result: APPROVED

Remarks:

Notes: 9/16/19; New house for 2020.tw

Inspection Type: FINAL**
Scheduled Date/Time: 9/16/2019
Completed Date/Time: 9/16/2019
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: Caulk toilets. Light to close to wall in master closet. Open washer drain.