



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

8/27/2019

SUBJECT: SFD1906-0026
SINGLE FAMILY DWELLING

To: AVILES FELICIANO

Here are the results of all Inspections located at **5675 CHRISTIAN LIGHT RD:**

Inspection Type: FINAL SFD CRAWL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: INSULATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: OPEN FLOOR
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: TAX INSPECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Tax Inspection
Result:
Remarks:
Notes:

Inspection Type: TEMP POWER CERTIFICATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: FOUNDATION SURVEY
Scheduled Date/Time:
Completed Date/Time:
Inspector: CP Bucket
Result:
Remarks: foundation survey needed
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: FOUNDATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Brad Sutton
Result:
Remarks:
Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 7/19/2019
Completed Date/Time: 7/19/2019
Inspector: GIS Bucket
Result: APPROVED
Remarks:
Notes: 5675 CHRISTIAN LIGHT RD FUQUAY VARINA 27526.
HOUSE BURNED THIS IS REBUILD.

Inspection Type: T-POLE
Scheduled Date/Time: 7/30/2019
Completed Date/Time: 7/30/2019
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks:
Notes: No premise # found

Inspection Type: FOOTING
Scheduled Date/Time: 7/30/2019
Completed Date/Time: 7/30/2019
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks:
Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time: 8/26/2019
Completed Date/Time: 8/26/2019
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: All piers shall be located on center 3rd of footing. Either move pier on get engineer repair letter to extend footing so pier is located in center 3rd.