

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

ENOCH
ENGINEERS, P.A.
1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT: Habitat for Humanity	DATE: 8.21.19
PROJECT: resi	CONTRACTOR: c/o Mike Blackman
ADDRESS: 807 Rosemary st	TECHNICIAN: BH
LOT #: Dunn, NC	

TEST SUMMARY

Performed footing bearing capacity evaluation at site noted above.
Soils confirmed a minimum allowable bearing capacity of 2000 psf at all footing locations.

TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.