

RJB, P.E., P.A.

C-0269

ROBERT J. BRACKEN
ENGINEER + SURVEYOR

3768 Caribon Road • Sanford, North Carolina 27330

April 7, 2020

Harnett County Building Inspections
P.O. Box 65
Lillington, NC 27546

REF: Compaction Test
371 Carolina Way
Sanford, NC 27332
Nash Locklear, Contractor

Dear Sir/Madam:

I made an onsite visit to the above referenced site on April 7, 2020. The purpose of the visit was to run compaction test on a porch. The soil was a sand clay mix and I ran soil bearing test using the hand held Penotrometer and got consistant readings of 2000 pounds per square foot or better. The compacted porch fill is adequate and meets the requirements set forth in the North Carolina State Residential Building Code, 2018,ed.

If you have any questions please feel free to call me at 919-774-6074.

Sincerely,



Robert J. Bracken, PE

RJB:jeb

