Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Sheet: Property ID: Lot #:

File #: Code:

SFD1967-0016

CROSS LINK

Address Propos Location Water Evalua	ss: 126 ecosed Facility: on of Site: Supply: tion Method f Wastewate	<i>38</i> √ 5	Design Property Public I		Well □ Spring □ Cut	ze: (), 58AC_		T 66	
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2,	L3%	6-26	GR LS	um uses					P.5
3		20.48	BN SLL	m wes		48			0.4
4	L 3%	0-36	CA LS	NOW NEW					ps
		36-48	on su	TA 5558		48			0.4
	- i - ii -		- /						
									2
	-								

Description	Initial	Repair System	Other Factors (.1946):	
	System		Site Classification (.1948):	Provisionally Svitube
Available Space (.1945)		1	Evaluated By:	
System Type(s)	25% Md	25% nd /50% A	Others Present:	Andrew Curtin, MEALS
Site LTAR	0.4	0.4		

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

**EXPANSIVE** 

C-CLAY SC-SANDY CLAY

IV

