

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.



1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: Dinh Tran	DATE: 8.12.19
PROJECT: Keith Hills s/d	CONTRACTOR: c/o Dinh Tran
ADDRESS: 2456 Keith Hills Dr.	TECHNICIAN: BH
LOT #: 93	

#### TEST SUMMARY

Performed footing inspection for determination of bearing capacity at site noted above. Soils confirmed a minimum allowable bearing capacity of 2000 psf. Backfill undercut footings with #57 stone to grade.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

#### RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:

*Disclaimer:*

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.

