Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet:
Property ID:
Lot #: AZZ
File #:
Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: App	olicant: Mamma	y Realty Homes Valuated: 9-25-19	,	
Address:	) 36'x (a) Date D	Flow (1949): 21 ACPI	Property Size:	
Location of Site:	Toursu To Proper	ty Recorded:	Troperty Size.	
Water Supply:	Public Inc	dividual Well	Spring	Other
Evaluation Method:	Auger Boring	☐ Pit ☐ Cut		
Type of Wastewater:	Sewage	☐ Industrial Process	☐ Mixed	

P R O F 1 .1940			SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (ln.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L 25%	0-48	GR LS	VFR SEXP	nsnd	48"			5
				•	,				
				(2)					
			100						
			***************************************		2 1				
						- 10 - 4			

Description	Initial	Repair System	Other Factors (.1946):
	System	70 0000	Site Classification (.1948): 5 wtable
Available Space (.1945)			Evaluated By: Britary Adams Others Present:
System Type(s)	251.000	25% Red	Others Present:
Site LTAR	0.8	0.8	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1

C-CLAY

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

