



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

12/11/2019

SUBJECT: SFD1909-0033
SINGLE FAMILY DWELLING

To: CAVINESS LAND DEVELOPMENT INC

Here are the results of all Inspections located at **511 ANGEL OAK DR:**

Inspection Type: ENV OPERATIONS PERMIT
Scheduled Date/Time:
Completed Date/Time:
Inspector: EH Bucket
Result:
Remarks:
Notes:

Inspection Type: FINAL SFD MONO**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: INSULATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: TAX INSPECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Tax Inspection
Result:
Remarks:
Notes:

Inspection Type: TEMP POWER CERTIFICATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: MONO SLAB SFD MONO
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks: eTRAKiT Inspection Request
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: UNDER SLAB TRADES
Scheduled Date/Time: 10/16/2019 Any
Completed Date/Time: 10/16/2019
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/15/2019 2:02 PM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

Inspection Type: ADDRESS
Scheduled Date/Time: 10/23/2019 Any
Completed Date/Time: 10/23/2019
Inspector: GIS Bucket
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/22/2019 10:09 AM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

511 ANGEL OAK DR BUNNLEVEL 28323.

Inspection Type: T-POLE
Scheduled Date/Time: 10/23/2019 Any
Completed Date/Time: 10/23/2019
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/22/2019 10:07 AM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: MONO SLAB
Scheduled Date/Time: 10/23/2019 Any
Completed Date/Time: 10/23/2019
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/22/2019 10:11 AM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

Inspection Type: MONO SLAB SFD MONO
Scheduled Date/Time: 10/24/2019
Completed Date/Time: 10/24/2019
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks:
Notes: Install rebar per Table 608.5.4(1) and Figure 608.5.4(1) also provide yield strength of rebar installed

Inspection Type: MONO SLAB
Scheduled Date/Time: 10/25/2019 Any
Completed Date/Time: 10/25/2019
Inspector: Slade Burton Lawson III
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/24/2019 1:48 PM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

Inspection Type: FOUNDATION SURVEY
Scheduled Date/Time: 11/1/2019
Completed Date/Time: 11/1/2019
Inspector: Donna Johnson
Result: APPROVED
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 12/9/2019 Any
Completed Date/Time: 12/9/2019
Inspector: Slade Burton Lawson III
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 12/3/2019 9:24 AM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

sbl changed Inspection Date/Time from 12/04/2019 Any to 12/06/2019 12:30 PM
12/4/2019 2:03 PM CAVINESS LAND DEVELOPMENT

Contact Name: CAVINESS LAND DEVELOPMENT
Site Address: 511 ANGEL OAK DR
Phone: 9193396330
e-Mail: janine@cavinessland.com

Missing joist hanger nails under stairs, drain test down, water supply test less than 100psi