## HAL OWEN & ASSOCIATES, INC.

## SOIL & ENVIRONMENTAL SCIENTISTS

P.O. Box 400, Lillington NC 27546-0400 Phone (910) 893-8743 / Fax (910) 893-3594 www.halowensoil.com

12 December 2016

Ms. Linda Thomas Johnson 14326 Salverdale Drive Dale City, Virginia 22193

Reference: Final Report for Comprehensive Soil Investigation Linda Johnson Property - 5.302 Acres

Dear Ms. Johnson,

A comprehensive soil investigation has been conducted at the above referenced property, located on the eastern side of Hoover Road (SR 1210), Barbecue Township, Harnett Ccunty, North Carolina. The purpose of the investigation was to determine the ability of this lot to support a subsurface sewage waste disposal system and repair area for a typical three-bedroom home. All soil ratings and determinations were made in accordance with "Laws and Rules for Sewage Treatment and Disposal Systems, 15A NCAC 18A .1900". This report represents my professional opinion as a Licensed Soil Scientist but does not guarantee or represent permit approval for any lot by the local Health Department. An improvement permit will need to be obtained from the Health Department that specifies the proposed home size and location, and the design and location of the septic system to be installed. It is our understanding that individual septic systems and public water supplies will be utilized at this site. The maximum house footprint used for this evaluation was 50 X 50 feet. Wetlands were not observed in the investigated portion of the property.

A portion of this lot was observed to be underlain by soils rated as provisionally suitable for subsurface sewage waste disposal. These provisionally suitable soils were observed to be firm silty clay loams to about 12 to 18 inches below surface. Loam textured saprolite materials were observed to greater than four feet. These materials appear adequate to support long term acceptance rates of 0.3 gal/day/sqft for conventional drainlines. The above referenced regulations require that pits be dug to properly evaluate these type materials. So please be advised that the health department will likely require you to provide a backhoe or other equipment to excavate pits when you apply for your permit to build. It appears that the soils on this lot are adequate to support a conventional septic system and repair area for at least one residence.

This soil investigation report and map, when provided to the Harnett County Health Department, should allow them to sign the maps for recordation. I appreciate the opportunity to provide this service and hope to be allowed to assist you again in the future. If you have any questions or need additional information, please contact me at your convenience.



Sincerely,

Hal Owen

Licensed Soil Scientist

