

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT: WELLONS REALTY	DATE: 2.27.20
PROJECT: PLANTERS GLEN S/D	CONTRACTOR: C/O DEWAYNE STEPH
ADDRESS: 60 WHEAT DR	TECHNICIAN: BH
LOT #: 4	

TEST SUMMARY

PERFORMED BEARING CAPACITY EVALUTAION AT SITE NOTED ABOVE.
 #57 STONE CONFIRMED A MINIMUM ALLOWABLE BEARING CAPACITY OF 2000 PSF AT
 FRONT PORCH BACKFILL. COMPLETE THE FRONT PORCH BACKFILLING PROCESS W
 #57 STONE OR A SUITABLE SOIL MATERIAL. NO COMPACTION REQUIRED ON
 #57 STONE.

TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

RETURN VISIT REQUIRED?

YES
 NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.