



FIELD REPORT

FOUNDATION DEPARTMENT

PROJECT NAME: <i>Carrage Circle</i>	PROJECT #: <i>6033-504</i>
PROJECT LOCATION: <i>Spring Lake, MI</i>	SUMMIT REPRESENTATIVE: <i>Andy</i>
DATE: <i>2/11/20</i>	PRESENT AT SITE:
CLIENT/CONTRACTOR: <i>Capital City</i>	MILEAGE:
WORK PERFORMED: <i>4H, 2P</i>	TOTAL TIME:

AS REQUESTED, SUMMIT REPRESENTATIVE REPORTED TO THE ABOVE REFERENCED SITE TO EVALUATE NEAR SURFACE FOUNDATION BEARING MATERIALS FOR THE PROPOSED:

LOT/BUILDING NUMBER: *1179*

ADDRESS: *24 Stone Hilltop Cir*

PERMIT NUMBER: *1412-0034*

OUR TESTING AND OBSERVATIONS INDICATE THAT THE SOILS TESTED BY SUMMIT ARE/ ARE NOT SUITABLE FOR THE MINIMUM ALLOWED BEARING CAPACITY OF *2,000* PSF AT THIS TIME

ACTION REQUIRED:

RETURN VISIT REQUIRED: YES/NO *(NO)* SIGNED (SUMMIT) *[Signature]*

SIGNED (CLIENT/CONTRACTOR IF REQUIRED) _____