



Wise Engineering
3915 Old Fairground Rd.
Angier, NC 27501
(919)894-2203

February 4, 2020

Gene's Backhoe Service
Tyler Nordan
1340 Two Claude Rd.
Willow Spring, NC 27592

Subject: 1156 Middle Rd, Dunn, NC 28334

Mr. Nordan,

A representative from Wise Engineering (WE) was on-site to observe the existing footing excavations at 1156 Middle Rd, Dunn, NC 28334 and to test the bearing capacity of the existing soil within the footings.

Based on the results of our field test, WE recommends that locations (specified while on-site) throughout the footing should be over excavated (3'-4' down to firm residual soil). The over excavated areas should be backfilled with clean washed stone (#57 or #78M) back to the plan specified footing elevation.

If you need additional information or have other questions, please let us know.

Sincerely,

Taylor Poulos

Randy K. Wise, PE

