

February 11, 2020

Mr. Austin Brown Capital City Homes 5711 Six Forks Road, Suite #200 Raleigh, North Carolina 27609

**Subject: Summary of Foundation Bearing Material Evaluation** 

> Lot No. 1099 – (113 Education Drive) **Academy at Anderson Creek Subdivision**

Spring Lake, North Carolina Permit Number: SDF1912-0038

**Project Number: 6603.500 (26742-00)** 

Dear Mr. Brown:

On February 5, 2020, SUMMIT Engineering, Laboratory and Testing, P.C. (SUMMIT) visited the subject site for the purpose of observing and evaluating the near surface foundation bearing materials for the proposed residential structure. The following is a summary of our onsite observations and evaluation

Our work included testing and bearing grade evaluations of the in-place soil at the bottom of the foundation excavations. Hand auger borings were incrementally advanced by manually twisting a sharpened steel auger into the soil at selected locations along the footing excavation. The soil consistency in the bottom of the excavation and at selected intervals below the bearing grade was evaluated by Dynamic Cone Penetrometer (DCP) testing. The conical point of the DCP was first seated to penetrate any loose cuttings and then driven three additional 1-3/4 inch increments with blows from a 15-pound hammer falling 20 inches. The soil's strength characteristics and foundation support capability was determined based on the average blows per increment (bpi) over the last two increments to achieve this penetration. Additionally, the entire excavated foundation was evaluated by hand probing using a ½ inch diameter steel probe rod to check for soft areas at the surface intermediate of our hand auger boring locations.

The materials encountered in our hand auger borings generally consisted of gray-tan, sandy-silt and sandy-clay (residual soils) and were free of significant quantities of organics and debris. It should be noted that standing water and wet soils were observed during our site visit. We recommend mucking out standing water and wet surficial soils prior to placing concrete. If additional testing for the purpose of estimating volumetric change (shrink/swell) potential or to estimate consolidation is desired, **SUMMIT** can provide these services.

Based on the results of our DCP testing, our site observations, and once the standing water and wet surficial soils have been mucked out, the soils encountered will be suitable for support of the residential structure utilizing a net allowable soil bearing pressure of **2,000 pounds-per-square-foot**.

If foundation bearing materials are exposed to inclement weather or adverse construction activities, **SUMMIT** should be contacted to re-evaluate the foundation bearing materials prior to concrete placement. If it is imminent that inclement weather is forecasted prior to concrete placement, then the footings can be over-excavated (deepened) approximately 2 to 4 inches and a mud-mat (lean concrete) can be placed up to the foundation bearing elevation to help protect the foundation bearing materials from softening.

**SUMMIT** appreciates the opportunity to provide our professional services to you on this project. If you have any questions concerning the information in this report or if we can be of further service, please contact us.

Sincerely,

Jeff A. Taylor, P.E.

Geotechnical Engineer

**SUMMIT** Engineering, Laboratory and Testing, P.C.

Adam D. Perry, E.I. Staff Professional