



March 31, 2020

Johnathan Wall
Johnathan Wall Custom Homes
1269 Turner Meadow Dr.
Raleigh, NC 27603
Email: Johnathanwallhomes@gmail.com

Reference: Engineering Services
109 Truelove Rd.
Holly Springs, NC 27540
Project No.: 2001-020203

As requested by the builder, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to inspect the following item(s):

1. Materials/conditions of the exposed footing excavations.

The following conclusions and recommendations were noted:

1. The materials/conditions of the exposed footing were visually observed and qualitatively probed. Based on our observations, analysis, and the result of our field-testing program, the existing/exposed footing excavations were noted as being adequate to support the anticipated loading conditions (2000 PSF).

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,
Tyndall Engineering & Design

Tripp Amos
TA | 2001-020203

Prentice A. Tyndall Jr., P.E.



