

Joe E Godwin Sr., P.E., P.L.S.

Fleet Temple, P.E.

Jason E Godwin, P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION FIELD REPORT

### PROJECT

CLIENT: STAND SURE HOMES

PROJECT: THORNTONS CRK S/D

ADDRESS: 61 THORNTONS CREEK

LOT #: 2

DATE: 10.7.20

CONTRACTOR: BILL GAINEY

TECHNICIAN: BH

### TEST SUMMARY

PERFORMED NDT ON PAD AT SITE NOTED ABOVE USING TARGET DENSITY OF 92 PCF.  
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	99.12	92.81	105.2	19.8

RETURN VISIT REQUIRED?

YES   
NO

TECHNICIAN:

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following report determined by a North Carolina Building Code enforcement official or Enoch Engineers, P.A. of any soil & material condition.