Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #:

500 2005-0003

File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant: Crecor I-C Owner: Date Evaluated: & \$114/2020 Design Flow (.1949): 360 GRS Address: Proposed Facility: 392 55 Property Size: 6.414c Location of Site: Public Individual ☐ Spring Other Water Supply: Evaluation Method: Auger Boring
Type of Wastewater: Sewage ☐ Pit ☐ Industrial Process Mixed

P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
,2	L 3-5%	0-28	ch is	un sol					PS.
		28-42	me su	F1 3558	7.5M1,042'	42			6.4
3	L 3-5%	0-18	61 LS	VA POSNO					
		18-38	BUSIL	FR 3358					Q.3
		38+	rack	_		36			0.4
		* *							
			14						

Description	Initial	Repair System	Other Factors (.1946):
VA	System		Site Classification (.1948): PADUISION XLLY DUITABLE
Available Space (.1945)			Evaluated By:
System Type(s)	25% NED	2590 MED	Others Present: AND NEW CURIN , NEW
Site LTAR	0.4	0.4	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I II	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE	11	L-LOAM	0.0 - 0.0	VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

CR-CRUMB GR-GRANULAR

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

MINERALOGY

SLIGHTLY EXPANSIVE

EXPANSIVE



