

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

ENOCH
ENGINEERS, P.A.
1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

| | |
|----------------------------------|--------------------------|
| CLIENT: FISHER BUILD GROUP | DATE: 9.21.20 |
| PROJECT: RESI STEM WALL BACKFILL | CONTRACTOR: DANNY FISHER |
| ADDRESS: 630 IRIS BRYANT RD DUNN | TECHNICIAN: BH |
| LOT #: | |

TEST SUMMARY

PERFORMED NDT ON PAD AT SITE NOTED ABOVE USING TARGET DENSITY OF 109 PCF
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

TESTING RESULTS

| SERVICE PERFORMED | TEST NO. | COMP % | WD PCF | DD PCF | MOISTURE % |
|-------------------|----------|--------|--------|--------|------------|
| NDT | 1 | 100+ | 112.0 | 117.6 | 4.94 |
| | | | | | |
| | | | | | |

RETURN VISIT REQUIRED?

YES


NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 90 days of the date of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.



9/21/20