

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

ENOCH
ENGINEERS, P.A.
1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT:	FISHER BUILD GROUP	DATE:	8.24.20
PROJECT:	RESI STEM WALL BACKFILL	CONTRACTOR:	DANNY FISHER
ADDRESS:	656 IRIS BRYANT RD DUNN	TECHNICIAN:	BH
LOT #:	6		

TEST SUMMARY

PERFORMED NDT ON PAD AT SITE NOTED ABOVE USING TARGET DENSITY OF 109 PCF
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	111.1	119.3	7.3

RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:




Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.