Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: 55 File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

System

Available Space (.1945) System Type(s)

Site LTAR

Owner: Applicant: Galt Land Development Address: Date Evaluated: 6/4/2020 Proposed Facility: 57 53 X50 Design Flow (.1949): 480 GPD Property Size: Location of Site: 16 Chartectory Property Recorded: Water Supply: Public Individual Well Spring Other Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process Mixed												
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS							
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR			
1,2	L 25%	0-48	GR LS	VIPE SOUP	nsmp	48"			8.8			
				,	,							
		11-20			0 10							
				- Constitution of the cons	2.2.2							
				0.00								
					4 M M M M M M M							
					4							
Description Initial Repair System Other Factors (.1946):												

Site Classification (.1948): 5

Others Present:

Evaluated By: PA

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ī	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

IV SIC-SILTY CLAY

C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

