Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet:
Property ID:
Lot #: 59
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Galt Land Development Address: Date Evaluated: 697270 Proposed Facility: Sp 51'x 39' Design Flow (.1949): 480670 Property Size: Location of Site: 804 Forest Property Recorded: Water Supply: Public Individual Well Spring Other Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process Mixed									
P R O F	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L 45%	0-48	GR LS	VFR SEXP	nsnp	48"			5
			V *;		7 / F / BA /-				
		8	-		*				
	-	67	đ.						
					8 *				

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)		. /	Evaluated By: BA
System Type(s)	257. Lex	1 25% Rea	Others Present:
Site LTAR	0.8	0.8	

gas an open was to the section of the

hogen hogels

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

SC-SANDI CLAI

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

