


Norris Farm 4-Bedroom Septic Proposal Lot #5

5

0.673 AC.
29302 SF



System: Pump to D-Box
Lines: 1-4 (300')
0.4 LTAR
24" Trench Bottom
Accepted Status System
Repair: Pump to D-Box
Lines: 5-7 (300')
0.4 LTAR
16" Trench Bottom
Accepted Status System

GRAPHIC SCALE
1" = 50'



Adams
Soil Consulting
919-414-6761
Job #574