Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Owner:

Description

System Type(s)

Site LTAR

Available Space (.1945)

Initial

System

25% NED

Repair System

25% NED

0.3

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant: DAKO RHN BUDS

Sheet: Property ID: Lot #:

File #:

Code:

SFD2008-0018

CLDE MILL

Address Proposi Location Water S	ed Facility: on of Site: Supply:	382	Date Desig Prope Public Irr Boring Sewage	Evaluated: A G In Flow (.1949): 30 Inty Recorded: Individual V Individual Industrial P	Property Siz	ze:		T 32		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1,2,3	L3-5%	0-12	GL 5L	11 5 P					PS	
		12-48	BU SEL	F1 5 P		48			0.3	
	2									
										1
										4
									 	\dashv
						1				_

Other Factors (.1946):

Evaluated By:

Others Present:

Site Classification (.1948): (NOUIS 10 NALLY SOITAGE?

ANDREW CORNO, MEHS

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

