Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #: SPD 2008-0071
Code: Lot 13

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Lanco Custom
Address: Date Evaluated: 9-28-29-20
Proposed Facility: SFD Design Flow (.1949): 300 Property Size:
Location of Site: Property Recorded:
Water Supply: ☑ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☑ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1,2 3	L	0-20	LS	FR OLNSOND					
		20-34	SL	"					
		34-48	SCL	SL FR W SBK SSSP	42 7.5yr 3.1				.5-.6

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	2SR	2SR
Site LTAR	.5	.5

Other Factors (.1946):
Site Classification (.1948): Y
Evaluated By: PS - JM
Others Present:


3
2
3R
5FD
1
cul De sac