Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: SFD 2010 - 00 34 Lot #:

Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

MRH lond				
MRH lond Owner: Holding App	licant:	11-2-7027		
Address:	Date E	Evaluated: 11-3-2020		
Proposed Facility: 5 FQ	_ Design	r Flow (.1949): 160 GPD	Property Size:	
Location of Site:		ty Recorded:		_
Water Supply:	№ Public Inc	dividual	Spring	Other
Evaluation Method:	Auger Boring	Pit 🗌	Cut	
Type of Wastewater:	😡 Sewage	Industrial Process	☐ Mixed	

P R O F I .1940		Horizon Depth (In.)		DRPHOLOGY 1941	OTHER PROFILE FACTORS				
L Landscape E Position/ # Slope %	.1941 Structure/ Texture		.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1-3	L 5-10%	0-6	LS (A) Gr	F-/NS/NP/NXP	>48"	>48"		_	S.8 Group I
	- 1	6-48	15 Gr	Folus /NP/NXP					I
									_

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: M born REHT
System Type(s)	252 111	25% red	Others Present:
Site LTAR	. 8	. 8	JM

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	<u>WET</u>
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	z. z	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1

C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

CR-CRUMB

GR-GRANULAR

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

