

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

**E**NOCH  
ENGINEERS, P.A.  
1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: CUMBERLAND HOMES	DATE: 2.11.21
PROJECT: SOUTH CREEK S/D	CONTRACTOR: AUSTIN PARKER
ADDRESS: 122 THUNDER VALLEY CT	TECHNICIAN: BH
LOT #: 75	

#### TEST SUMMARY

PERFORMED NDT ON STEMWALL SOIL BACKFILL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 120 PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

#### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	95.47	114.4	115.3	0.8

#### RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying