

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION FIELD REPORT

PROJECT

CLIENT: CUMBERLAND HOMES

DATE: 2.11.21

PROJECT: SOUTH CREEK S/D

CONTRACTOR: AUSTIN PARKER

ADDRESS: 154 HEATH DR

TECHNICIAN: BH

LOT #: 48

TEST SUMMARY

PERFORMED NDT ON STEMWALL SOIL BACKFILL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 120 PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	98.91	118.7	124.9	5.2

RETURN VISIT REQUIRED?

YES
NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying