



# FIELD REPORT

## FOUNDATION DEPARTMENT

PROJECT NAME: <i>Carriage Circle</i>	PROJECT #: <i>6055</i>
PROJECT LOCATION: <i>Spring Lane</i>	SUMMIT REPRESENTATIVE: <i>A.B.</i>
DATE: <i>7/15/21</i>	PRESENT AT SITE:
CLIENT/CONTRACTOR: <i>Capital City</i>	MILEAGE:
WORK PERFORMED: <i>Re-inspection</i>	TOTAL TIME:

AS REQUESTED, **SUMMIT** REPRESENTATIVE REPORTED TO THE ABOVE REFERENCED SITE TO EVALUATE NEAR SURFACE FOUNDATION BEARING MATERIALS FOR THE PROPOSED.

LOT/BUILDING NUMBER: *1162*

ADDRESS:

PERMIT NUMBER:

OUR TESTING AND OBSERVATIONS INDICATE THAT THE SOILS TESTED BY **SUMMIT** (ARE) ARE NOT SUITABLE FOR THE

MINIMUM ALLOWED BEARING CAPACITY OF *2000* PSF AT THIS TIME.

ACTION REQUIRED:

*SUMMIT absence re-insp.*

RETURN VISIT REQUIRED: YES/NO *NO*

SIGNED (SUMMIT)

SIGNED (CLIENT/CONTRACTOR IF REQUIRED)

**ENGINEERING • LABORATORY • TESTING**

3070 HAMMOND BUSINESS PLACE • SUITE 171 • RALEIGH, NC 27603 • (919) 380-9991 • (919) 380-9993 (FAX)  
[WWW.SUMMIT-COMPANIES.COM](http://WWW.SUMMIT-COMPANIES.COM)