

# Wayne R. Dashfield, PE

421-B North Bright Leaf Blvd. Smithfield, NC 27577

(919) 934-0961

February 24, 2021

Re: 3005 Fair Ground Road  
Dunn, NC

To: Harnett County Inspections

Dear Sir, Madam

On February 24, 2021 I made an on-site visit to 3005 Fair Ground Road in Dunn, N.C. The purpose of this visit was to make a structural inspection of the placements of the headers located over the windows and doors in the load bearing walls. During one of the inspections the Harnett County Building Inspector noted the headers were installed with a double header with the trimmer studs located below the headers and requested that an engineer verify that this method is adequate. During my inspection of the headers I found that the loading on the proper sized headers supported by the required full-height jack studs is adequate.

Based on the loadings and the location of the headers I will certify that the headers are adequate. The 2018 Residential Building was used for this inspection.

If I can be of any more assistance please feel free to contract me.

Yours truly,

Wayne R. Dashfield, PE



WY 02/25/21

# Wayne R. Dashield, PE

421-B SOUTH BRIGHTLEAF BLVD  
Smithfield, NC 27577  
(919) 934-0961 fax (919) 934-0967

Invoice No. *JRT-HSE-INSP-INV-01*

## INVOICE

### Customer

Name	JRT MANGEMENT PROPERTIES		
Address	_____		
City	DUNN	State	NC
Phone	_____		

Date	2/25/2021
Order No.	_____
Rep	_____
FOB	_____

Qty	Description	Unit Price	TOTAL
1	ONSITE VISIT 02/24/21	\$100.00	\$100.00
1	CERTIFY LETTER 04/2/19	\$200.00	\$200.00

<b>Payment Details</b>
<input checked="" type="radio"/>
<input type="radio"/>
<input type="radio"/>
_____
_____
_____

SubTotal	\$300.00
Shipping & Handling	\$0.00
Taxes	\$0.00
<b>TOTAL</b>	<b>\$300.00</b>

Office Use Only
-----------------

3005 FAIR GROUND ROAD, DUNN,,NC

THANK YOU FOR YOUR BUSINESS