Harnett County Department of Public Health

PERMIT # SFD 2012-0648 Uperation Permit
New Installation 🔀 Septic Tank 🖄 Nitrification Line 🗆 Repair 🗆 Expansion
PROPERTY LOCATION: 396 MILL BEND OR.
Name: (owner) DAN RYAN GUSS SUBDIVISION GUSE MILL LILLAGE LOT # 44
System Installer: Com Promerose
Basement with plumbing: Garage Mumber of Bedrooms Function of Water Supply: Community Mumber of Bedrooms Function of Water Supply: Community Mumber of Bedrooms Function of
System Type: 2576 1250270 575724 TTT Types V and VI Systems expire in 5 years.
(In accordance with Table V a) Owner must contact Health Department 6 months prior to expiration for permit renewal.
(in accordance with table 7 a)
This system has been installed in compliance with applicable North Carolina General Statutes, Rules for Sewage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authorization.
* INSTALL: 06/01/2021
* SENINE DISTURBUTION
CHIEMBER CONVECTES
H' X LINE I DIEZPER WE APPROX. 28IN FIRST 20.30FT
H' X LINE I DEEDER
5 9 (1 LD APPROX. 25TA) EPIST
26.30FT
5 2 2 6 7
[3] [7] []
3 8 0 CP
40'
TUS
50 SFD
39' 45'
9,5 35
PERMIT CONDITIONS: MILL BEND DRIVE
I. Performance: System shall perform in accordance with Rule .1961.
II. Monitoring: As required by Rule .1961.
III. Maintenance: As required by Rule .1961. Other: Subsurface system operator required? Yes No No
If yes, see attached sheet for additional operation conditions, maintenance and reporting.
IV. Operation:
V. Other:
Following are the specifications for the sewage disposal system on the above captioned property.
Type of system: Conventional Other O4 CHAMBER TUG Septic Tank: Conventional Pump Tank: gallons gallon
Subsurface No. of exact length width of depth of
Drainage Field ditches 5 of each ditch 82 feet ditches 3 feet ditches 24 inches
French Drain Required: Linear feet
Authorized State Agent Date 06/01/2021
ribulionized state regent