Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #:

File #: Code:

AD 5103-0014

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: \$\frac{350}{50} \frac{50}{50} \frac{1}{50} \frac{1}{50}

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1, 2	7	0-8	15(A) Gr	Fr/NS/NP/NXP	~48"	248"	_		P5-4
	2-5%	8-20	15 Gr	Fr/NS/NP/NXP					PS.4 Group
		20-48	sci spk	Fi  SS SP SXP	J48" (Franch Do	ain)			
				111					
					7 .				
					,				
						- 1	-		
						3-2			
					on side of				
						\$			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	-	-	Evaluated By: Mesber REHs
System Type(s)	25% md	252120	Others Present:
Site LTAR	.4	- U	(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY SC-SANDY CLAY

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

GR-GRANULAR SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 100 0 130

9 3 4 9 9 1 1 1