

Project 13-1 FOREST RIDGE Project No. \_\_\_\_\_  
 Location 430 MELODY LN Date \_\_\_\_\_  
 Client \_\_\_\_\_ Temp/Weather \_\_\_\_\_  
 Permits \_\_\_\_\_ Arrive \_\_\_\_\_  
 Task \_\_\_\_\_ Depart \_\_\_\_\_  
 No. of Trips \_\_\_\_\_ On-Site Time \_\_\_\_\_ Travel Time \_\_\_\_\_  
 Total Mileage \_\_\_\_\_ Lab/Office Time \_\_\_\_\_ Total Time \_\_\_\_\_  
 Reinspection Time \_\_\_\_\_  
 Project Manager \_\_\_\_\_  
 Technician KYRA

2:30-  
 3:30

Design Bearing Capacity (psf) 2000  
 Pass   
 Fail \_\_\_\_\_

**RESULTS & RECOMMENDATIONS**

1 FOOTING  
 HAD CONTRACTOR  
 REMOVE STONE TO  
 DO 2 TESTS  
 BOTH PASSED

**PROJECT MANAGER REMARKS**

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_