

Harnett COUNTY INSPECTIONS DEPARTMENT

3RD PARTY INSPECTION FORM

RECORD OF THE INSPECTION OF A COMPONENT OR ELEMENT BY A NC LICENSED ARCHITECT OR ENGINEER

Project Information:

Residential Single Family Project: Y N Commercial Project: Y N
Code Enforcement Project No.: Permit No.:
Project Name: Owner:
Project Address: Suite No.:
Date Inspected: Contractor Name:
Component Inspected:

Responsible Licensed NC Architect or NC Engineer

Name:
Firm Name:
Phone No.: Office Mobile
Email Address:
Mailing Address:

APPLICABLE CODE SECTION:


2018 NCBC = 2018 NC Building Code; 2018 NCRC = 2018 NC Residential Code

Describe Element/Component/Type of Inspection: *

*(subgrade form/letter may also be required) Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per subsection (b2) of NC G.S. 153A-352 and is in compliance with the Code or other proposal of the architect or engineer for the project. This inspection is in compliance with all of the requirements of the above referenced Code. Attach any additional documents if needed.

LICENSED ARCHITECT OR ENGINEER



Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of Article 160A-413.5., Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.



DAILY REPORT

Project No. 201253x093
 Project Name: 2184 Wire Road, Bunnlevel, NC
 Client: McGee Brothers / Schumacher Homes
 Technician: SS

Date: 10/17/2023
 Day: Tuesday
 Weather: _____
 Temperature: _____ °F

Soil Type: _____
 Max. Dry Density: _____
 Optimum Moisture: _____
 Nuclear Gauge: Soil
 Asphalt
 None

Arrived On-Site: _____ am
 _____ pm
 Departed Site: _____ am
 _____ pm
 Mileage: _____

On-Site Time: _____
 + Travel Time: _____
 - Lunch: _____
 Total: 0

LOCATION OF WORK

2184 Wire Road, Bunnlevel, NC

DESCRIPTION OF WORK

- (Permit No.: SFD2104-0032)

GTA representative arrived on-site on June 26, 2023, as requested, to observe the application of waterproofing materials for below grade walls at the residential home located at the lot/address referenced above.

Please see the above physical site address and building permit number for the lot observed on this date.

Based on GTA visual observations at the time of our site visit, Tremco waterproofing materials and associated drainage stone/pipe were observed, and generally appeared to have been installed in conformance with the 2018 North Carolina Residential Code.


ISSUES/DEFICIENCIES/FAILING TESTS

Attachments: Nuclear Field Density Worksheet Sand Cone Worksheet Moisture Density Curve Oversize Correction Photos
 Location Sketch Subgrade Preparation Report Foundation Observation Report Concrete Test Report Material tickets
 Other _____

Technician
 Signature/Initials: SS

Reviewer: W. Shawn Sullivan, P.E.

Signature/Initials: _____



GTA Associates, Inc.


10/17/2023 | 6 Photos



2184 Wire Road, Bunnlevel, NC Waterproofing Observation Letter


Waterproofing Material Observation Photographs

drainage board, drainage stone, perforated pipe



Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan



Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan



Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan



Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan



5

Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan



6

Waterproofing Materials/Application Observed

Project: 2184 Wire Road, Bunnlevel, NC
Date: 10/17/2023, 12:03pm
Creator: Shawn Sullivan