Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: CONSTAN Applicant: Address: 3695 Pondersa Ad	Date Evaluated: 6-6-22		
Proposed Facility: (F)	Design Flow (.1949): 4180 GPD	Property Size:	
Location of Site: Water Supply: ☑ Public	Property Recorded: Individual Well	☐ Spring	Other
Evaluation Method: Auger Boring Type of Wastewater: Sewa	ge Pit Cut Industrial Process	☐ Mixed	

	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Consistence Texture Mineralogy		.1941	OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr				Profile Class
,2	1	0-18	25	G-	Fr	10 y R 6/1	Depth (IN.)	Class	Horiz	P5.4
	L 2-5%	18-48	sec s	szu	Fi	10YR 6/1 > 26"				& LTAR PS. 4
										-
		1								
		14,								
		-				-				
					ň		i)			
		9			<i>.</i> *					
					.'	,	2 -			-
	-									

Description	Initial	Repair System	Other Factors (.1946):	05	
	System	55.0	Site Classification (.1948):	1/ 2500	
Available Space (.1945)		V.	Evaluated By:	MOLE HS	
System Type(s)	25 % red	25% red	Others Present:		
Site LTAR	.4	.4			

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY IV

C-CLAY


SC-SANDY CLAY

0.4 - 0.1

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE



Pondwora Rd