

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.

**E**NOCH  
ENGINEERS, P.A.  
1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: TMD	DATE: 8.10.21
PROJECT: SOUTH CREEK S/D	CONTRACTOR: DENNIS NORRIS
ADDRESS: 94 HAZELWOOD DR	TECHNICIAN: BH
LOT #: 69	

#### TEST SUMMARY

PERFORMED SOIL BEARING CAPACITY EVALUATION OF FOOTINGS AT SITE NOTED ABOVE. RECOMMEND UNDERCUTTING REAR MARKED FOOTING AN ADDITIONAL 18" TO ACHIEVE MINIMUM ALLOWABLE BEARING CAPACITY OF 2000 PSF. BACKFILL UNDERCUT WITH WASHED #57 STONE TO GRADE.

#### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

#### RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:



*Disclaimer:*

Soils & Material inspections, testing results and on-site determinations contained in this report become void if there is non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.

