

Joe E Godwin Sr. , P.E., P.L.S.

Joe E Godwin Jr. , P.E.

Jason E Godwin , P.L.S.



1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT:	WATERMARK HOMES	DATE:	3.1.22
PROJECT:	BALLARD WOODS S/D	CONTRACTOR:	JT
ADDRESS:	425 JOSEPH ALEXANDER	TECHNICIAN:	BH
LOT #:	156		

#### TEST SUMMARY

PERFORMED NDT ON SOIL BACKFILL INSIDE STEM WALL USING A TARGET DENSITY OF 115 PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	115.3	122.3	6.0

DS


#### RETURN VISIT REQUIRED?

YES

NO

DocuSigned by:

339EA4405059480...



TECHNICIAN:

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying