


www.harnett.org

July 28, 2021

Cumberland Homes, Inc. PO Box 727
Dunn NC 28335



Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

ph: 910-893-7547 fax: 910-893-9371

AUG 02 2021

Re: Status of Improvement Permit Application: SFDS2107-0043

To whom it may concern:

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- ____1. Use pink flags to mark property lines and irons that are set by surveyor need to be visible. (\$25.00 fee incurred)
 - 2. Use orange flags to mark house corners (\$25.00 fee incurred)
- 3. Directions not clear to property (\$25.00 fee incurred)
- Property needs only brush or vegetation removed
- 5. Driveway not shown on site plan
- Backhoe pits required

X 7. Other-Soil Scientist Proposal required – Shallow unsuitable soils present on front of lot and unsuitable wet soil and topography on back portion of property. Soil Scientist proposal and layout required with application.

Additional requirements: Due to property line lengths into woods. Side property lines shall be cleared to allow a line of site and/or line shall be marked/staked by a surveyor. Pre-existing retention pond was onsite. Edge of disturbed area shall be marked onsite and documented accordingly. Retention pond was placed in area of limited soil availability.

Your application will be put on hold until the selected items above have been addressed. When completed, **please call 910-893-7547 to confirm** that the items mentioned have been corrected. We will then reschedule your property for evaluation.

Sincerely.

Andrew Currin, R. E. H. S.

Environmental Health Program Specialist Harnett County Department of Public Health

AC/slc

Copy: Central Permitting

strong roots · new growth

SOUTHEASTERN SOIL & ENVIRONMENTAL ASSOC., INC.

PROPOSED SUBSURFACE WASTE DISPOSAL SYSTEM DETAIL SHEET

	SUBDIVISION: BALLAND WEDDS		LOT /15
	INITIAL SYSTEM: APPROVED 25% REDUCT	<u>ION</u>	REPAIR APPROVED 25%. DEDUCTION
	DISTRIBUTION: SEPINA	******	DISTRIBUTION SERIAL
	BENCHMARK: 100.0	-	LOCATION FC 114/115
	NO. BEDROOMS: 3		LTAR 0.8 SPO /FTL
	LINE FLAG COLOR	ELEVATION	<u>LENGTH</u>
Lal	51 R	89.30	
In tal	22A Y	88,50	80' 40'
51			1201
	2B Y 3	88,50	40'
	3 R	87,20	80′
			110'
	BY MEAUER		DATE 8/14/21
	TYPICAL PROFILE (MOST CIMITING)		THERE SHALL BE NO GRADING,
	0-46 S/LS (VF-, wg.)		CUTTING, LOGGING OR OTHER SOIL
	46-48 su (Fi, shu)		DISTURBANCE IN SEPTIC AREA
	cr 2 > 484	j	HEALTH DEPARTMENT USE ONLY.
	INTALL AT 184 LEFT SI	PE (FACING,	DESIGNS DO NOT GURANTEE FUNCTIONALITY
	WILL BE AT 24" MOHT	SIDE / FAC	INE)


Southeastern Soil & Environmental Associates, Inc. P.O. Box 9321

P.O. Box 9321
Fayetteville, NC 28311
Phone/Fax (910) 822-4540
Email mike@southeasternsoil.com


BAUARD WOODS
LOT 115

PROPOSED SEPTIC

LAYOUT



1"=40"



JOSEPH ALEXANDER DRIVE

CUMBERLAND HOMES, INC.
THE TIFFANY
LOT # 115 BALLARD WOODS
SCALE: 1"=40'

