Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: JJJ App Address: 80 G/e	olicant:	e Evaluated: 4	9-22-71		
Proposed Facility: 4	52 SFD Des	ign Flow (.194	19): 360	Property Size:	
Location of Site: Water Supply:	Proj ✓ Public □	perty Recorded Individual	l: Well	☐ Spring	Other
Evaluation Method: Type of Wastewater:	Auger Boring Sewage	☐ Pit ☐ Indu	strial Process	Cut Mixed	
VI	_	_			

P R O F	Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941			OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture		.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2,3	. 1	032	15	Gr	Fr/ws/wdwa	>48"	148"			5.7
	5-7%	32-48	SL	G-	Fr/ws/welver					& LTAR S. 7 Gro-p IL
					э.					
					Ĭ.		. 1			
						×				
							(*)			
			,			4.				
						,				

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	1	-	Evaluated By: M REH
System Type(s)	25% med	25% med	Others Present:
Site LTAR	, 7	- 7	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6		S-STICKY VS-VERY STICKY NP-NON-PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

SIC-SILTY CLAY 0.4 - 0.1 ΙV C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

