Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: JSJ App	olicant:	e Evaluated: 10 -22 - 21		
Proposed Facility:	IFD Des	sign Flow (.1949): 480 GPD	Property Size:	
Location of Site: Water Supply:	Proj ▶ Public □	perty Recorded: Individual Well	☐ Spring	Other
Evaluation Method:	Auger Boring	☐ Pit ☐ Cut		
Type of Wastewater:	Sewage Sewage	☐ Industrial Process	☐ Mixed	

P R O F I .1940 L Landscape E Position/ # Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1,2	۷	0-27	W Gr	Folialis	248"	>48"	_	_	5.6 GAUP TL
	5-78	27-48	1L Gr	Folial No line					GAUP
				\$		F 1	1		
					*				
					* 4				
					1, 10			*	
					1	*			
							ŧ		

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):	5,1
Available Space (.1945)	-	_	Evaluated By:	MURET
System Type(s)	22814	252 red	Others Present:	
Site LTAR	. 6	. 6		

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SC-SANDY CLAY

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY

IV

