Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Duckworf Address: 2769 (D:	ate Evaluated: //-8-21		
Proposed Facility:	SFD De	esign Flow (.1949): 360 61	Property Size:	
Location of Site: Water Supply:	Public _		Spring	Other
Evaluation Method: Type of Wastewater:			Cut Mixed	

P R O F I	.1940		SOIL MORPHOLOGY .1941			OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	Str	1941 ucture/ exture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
3,4	1	0-16	41	G-	F-/w/welved	>48"	>48"	_	_	& LTAR PS. 5
	5-72	16-48	SCI	SBh	F-/23/50/50					-TH
									_	
	la.				v =		E S			
	7				,	* -	1			
	-					1 2 2 1				
						1.				
							4			
						-				

Description	Initial	Repair System
Available Space (.1945)	System	
System Type(s)	252 md	25% red
Site LTAR	-5	. 5

Other Factors (.1946): Site Classification (.1948): Evaluated By:

Evaluated By: Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ĭ	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM	S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PB. PBISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

