Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #:

File #: Code:

SF02110-0115

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: - Applicant: D. 1. HOLTON INC		LATATIETE MELDOW
Address: 68 OUD MARLIES Date Evaluated: 11/19/202)	Property Size:	LOT 19
Location of Site: Property Recorded: Water Supply: Public Individual Well Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process	☐ Spring	Other

L La E Po	.1940	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
	Landscape Position/ Slope %		.1941 Structure/ Texture	Cor	1941 nsistence neralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,12	L 3%	0-14	62 LS	W	NSNP			2	1	₽≤
		14-44	msu	FN	50	7.5+24,04211	44			0.3

Description	Initial	Repair System	Other Factors (.1946):		
	System		Site Classification (.1948):	PRODISONALY	SUITABLE
Available Space (.1945)			Evaluated By:		WARLIN, NEHS
System Type(s)	2590 20	25/0 NED	Others Present:	ANGREW	( )
Site LTAR	0.3	6.3			

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY


SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SPIK SUPPLY AND TO COME

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMA MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 



NO

OUD MAPLE