

## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

10/17/2022

SUBJECT: **SFD2111-0010** 

SINGLE FAMILY DWELLING

To: WESTER CONSTRUCTION CO INC

Here are the results of all Inspections located at 646 SPRING HILL CHURCH RD:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Scott Guy

Result: Remarks: Notes:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: Completed Date/Time:

Inspector: CP Bucket

Result:

Remarks: not required

Notes:

Inspection Type: FINAL SFD CRAWL\*\*

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 11/3/2021
Completed Date/Time: 11/4/2021
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 646 SPRING HILL CHURCH RD LILLINGTON 27546.



## Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 1/13/2022
Completed Date/Time: 1/13/2022
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 1/13/2022
Completed Date/Time: 1/13/2022
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time: 2/11/2022
Completed Date/Time: 2/11/2022
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 3/1/2022
Completed Date/Time: 3/1/2022
Inspector: Steven Gazlay
Result: CANCELLED

Remarks:

Notes: customer cancelled 2/28/22

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 3/3/2022
Completed Date/Time: 3/3/2022
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:



## **Harnett County**

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: **ROUGH IN** Scheduled Date/Time: 4/21/2022 Completed Date/Time: 4/21/2022 Inspector: James T Hall **DISAPPROVED** Result:

Remarks:

Notes: 1.Nail all 2&3 ply lvl beams every 12" per documents. 2.Missing all exterior doors. 3.100 psi on

water line test gauge broke was reading 120 after I took it off . 4. Missing hurricane straps on 3ply girder truss in master bedroom per truss documents. 5.Fire caulk wire @ bottom plate in master toilet room. 6.Strap each end of IvI beam in master bedroom. 7.Missing nail guard on 3" pipe & water line in stairway. 8. Missing bracing on trusses check truss documents. 9. Need compaction letter for all porches over 2' fill per code. 10.Strap duct trunk lines under house

every 64" per code.

Inspection Type: **ROUGH IN** Scheduled Date/Time: 5/6/2022 Completed Date/Time: 5/6/2022

Inspector: Slade Burton Lawson III

Result: **APPROVED** 

Remarks:

Notes:

Inspector SBL changed the inspection assignment from SBL to SPG

Inspector SPG changed the inspection assignment from SPG to SBL

Inspection Type: **INSULATION** Scheduled Date/Time: 6/9/2022 Completed Date/Time: 6/9/2022

Slade Burton Lawson III Inspector:

Result: **APPROVED** 

Remarks:

Notes: Inspector SPG changed the inspection assignment from SPG to SBL

Inspection Type: **ENVIR OPERATIONS PERMIT** 

Scheduled Date/Time: 8/15/2022 Completed Date/Time: 8/16/2022 Inspector: Mark Osborne Result: **APPROVED** 

Remarks: Notes:



## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: GAS PIPING
Scheduled Date/Time: 10/6/2022
Completed Date/Time: 10/6/2022
Inspector: James T Hall
Result: APPROVED

Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 10/10/2022
Completed Date/Time: 10/10/2022
Inspector: John B Kokoszka
Result: APPROVED

Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 10/10/2022
Completed Date/Time: 10/10/2022
Inspector: John B Kokoszka
Result: APPROVED

Remarks: Notes:

Inspection Type: FINAL SFD CRAWL\*\*

Scheduled Date/Time: 10/14/2022 Completed Date/Time: 10/14/2022 Inspector: James T Hall Result: DISAPPROVED

Remarks:

Notes: Inspector JBK changed the inspection assignment from JBK to JTH

1.Missing shower door in master bathroom and need to grout tile work around tub.2.Leak under master bath sink.3.Missing backsplash in kitchen sink.4.Seal holes under kitchen sink in cabinet.5.Need 30" platform at air handling unit in attic.6.Need 6 inches within 10 foot grade away from house.7.There are two wires under the house not in box ones to a floor receptacle the other is to the dishwasher.8.The dirt under the house needs to be graded where flow to low point in the crawlspace.9.Label condensing units up and down.Sent from my iPhone

