

Joe E Godwin Sr. , P.E., P.L.S.

Joe E Godwin Jr. , P.E.

Jason E Godwin , P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: SOUTHERN TOUCH  
PROJECT: MONO PAD FILL  
ADDRESS: MICROTOWER RD  
LOT #: 3-B

DATE: 2.9.22  
CONTRACTOR: BRYANT LOCKAMY  
TECHNICIAN: BH

#### TEST SUMMARY

PERFORMED NDT ON MONO SLAB SOIL FILL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 115 PCF.  
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

PROCESSED FILL MATERIAL\*


#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	116.2	118.8	2.5


#### RETURN VISIT REQUIRED?

YES   
NO

TECHNICIAN:




DocuSigned by:



339EA4405059480...

2/15/2022

DS



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.