Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: H+H Applicant: Address: 268 Bunting Dr Proposed Facility: SFD	Date Evaluated: //- 29 - 21 Design Flow (.1949): 480 GPD	Property Size:	
Evaluation Method: Auger Borin	Property Recorded:    blic	☐ Spring ☐ Mixed	Other

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			Stru	941 cture/ xture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,3	L	0-26	45	Gr	Folisherphys	>48"	>48"	_	_	5.6
	5-78	26-48	SL	Gr	Folusholuse Folusholuse					Group
						,				
					100	9				
					12 T	1				
				7	**	* x				
					· · · · · · · · · · · · · · · · · · ·					
					1	, i				

Description	Initial	Repair System	Other Factors (.1946):
9	System		Site Classification (.1948):
Available Space (.1945)	-	L 1	Evaluated By: MILLERS
System Type(s)	25 % rad	25% nd	Others Present:
Site LTAR	- 6	. 6	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I II	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

