Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Wlaw Ap Address: 200 Josep	oplicant:	Pate Evaluated: 7-21-22		
Proposed Facility:	A) D	Design Flow (.1949): L(80 GPD	Property Size:	
Location of Site: Water Supply:	P	roperty Recorded:  Individual Well	☐ Spring	Other
Evaluation Method: Type of Wastewater:		☐ Pit ☐ Cut	☐ Mixed	

P R O F I .1940		Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E Position De	.1941 Structure/ Texture		.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1,2	L	0-14	U 60	F/25/18/1X8	104R6/2>	>48"	_	_	PS.4 Golf
	2-54	14-48	Sci SBk	Filspelixe	104R6/2>				GOUP
				. 9	· ·	ರ್ಷ-ಎಂದರೆ			
				181					
					7				
				\$	1,21				
				ia.					
			3				- 1		

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	V		Evaluated By:
System Type(s) Pump	25% Red	25% 10	Others Present:
Site LTAR	.4	. 4	


COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFFEATREMEET FIRM	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
	IV	SIC-SILTY CLAY C-CLAY SC-SANDY CLAY	0.4 - 0.1		

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUIRANGLII AR MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PL-PLATY



Josey Williams Rd