RIB, P.E., P.A.

ROBERT J. BRACKEN ENGINEER + SURVEYOR

3768 Carbonton Road • Sanford, North Carolina 27330

April 11, 2022

Harnett County Building Inspections P.O. Box 65 Lillington, NC 27546

REF: Compaction Test
Residential Building Site @
176 Josey Williams Rd
Erwin, NC 28339
Weaver Homes, Contractor

Dear Sir/Madam,

I made an onsite visit to the above referenced residential building site on April 11, 2022. The purpose of the visit was to do soil bearing test for a slab and footing. The fill area was approximately 3' deep and filled with stone screenings. The material and compaction used was adequate and I used a hand held Penotrometer at several locations and got consistant readings of the Code approved Presumptive bearing pressure of 2000 psf. The compacted fill material will support the live and dead loads per the NC State Residential Building Code, 2018,ed. for a monolithic Slab.

If you have any questions please feel free to call me at 919-774-6074.

Sincerely,

Robert J. Bracken, PE

DESIGN PROFESSIONAL INSPECTION FORM

RECORD OF THE INSPECTION OF A COMPONENT OR ELEMENT BY A NC LICENSED ARCHITECT OR ENGINEER

Project Information:			
Residential Single-Family Pro		Commercial Project: Y	
Code Enforcement Project No:		Permit No:	
Project Name: Residence @ 104 Josey Williams Rd		Owner:	
Project Address:		Suite No:	
176 Josey Williams Rd, E			
Date Inspected: April 11, 2022		Contractor Name: Weaver Homes	
Component Inspected: So	oil Backfill		
Responsible Licensed NC .	Architect or NC	Engineer	
Name: Roberet J Bracken		ingine.	
Firm Name:	RJB,PE,PA		
Phone Numbers:	Office: 919-774-6074 Mobile: 919-770-0809		
Email Address:			
Mailing Address:	bjbracken@windstream.net 3768 Carbonton Rd, Sanfod, NC 27330		
	3700 Carbonion K	id, Samod, NC 27550	
APPLICABLE CODE: 2018 NCBC = 2018 NCBC = 2018 NC Buildin Describe Element/Compo (See Attached Letter)	g Code; 2018 NCR	C = 2018 NC Residential Code ection: *	
has been inspected by me or 352 and is in compliance wit	at the component of r someone under m th the Code or othe ce with all of the re	and/or element of the building as identified or by direct supervision per subsection (b2) of NC (er proposal of the architect or engineer for the equirements of the above referenced eded.	G.S. 153A
Robert J Bracken, PE Licensed Architect or Eng		2022 SPAL BR	NO N

Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of Article 160A-413.5.. Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.

12/2019