

Joe E Godwin Sr. , P.E., P.L.S.

Joe E Godwin Jr. , P.E.

Jason E Godwin , P.L.S.

**E**NOCH  
ENGINEERS, P.A.  
1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: WATERMARK HOMES

DATE: 9.12.22

PROJECT: OAK HAVEN S/D

CONTRACTOR: JT

ADDRESS: 79 BUCKHAVEN DR

TECHNICIAN: BH

LOT #: 33

#### TEST SUMMARY

PERFORMED NDT ON SOIL BACKFILL INSIDE STEM WALL USING A TARGET DENSITY OF 118 PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.


#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	121.7	136.3	3.7

#### RETURN VISIT REQUIRED?

YES

NO



9.12.22

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying