



**Harnett County**  
420 McKinney Pkwy  
LILLINGTON, NC 27546  
Phone:  
Fax:

8/29/2024

**SUBJECT: SFD2202-0024**  
**SINGLE FAMILY DWELLING**

To: Luis Sanchez

Here are the results of all Inspections located at **68 ROBINSON LN:**

Inspection Type: FOUNDATION SURVEY  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: CP Bucket  
Result:  
Remarks: eTRAKiT Inspection Request  
Notes: 8/27/2024 8:42 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: ADDRESS  
Scheduled Date/Time: 2/8/2022  
Completed Date/Time: 2/8/2022  
Inspector: GIS Bucket  
Result: APPROVED  
Remarks:  
Notes: 68 ROBINSON LN ANGIER 27501. MUST POST ADDRESS SIGN / WITH ARROW AT CURVE ON ROBINSON LN FOR THIS LONG DRIVE WAY TO ENSURE LOCATION FOR FIRE/EMS.

Inspection Type: FOOTING  
Scheduled Date/Time: 1/24/2023  
Completed Date/Time: 1/24/2023  
Inspector: Scott Guy  
Result: APPROVED  
Remarks:  
Notes:



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: FOUNDATION  
Scheduled Date/Time: 2/10/2023  
Completed Date/Time: 2/10/2023  
Inspector: Scott Guy  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 2/7/2023 8:50 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Address unbalanced backfill on front porch if this is done.

Inspection Type: OPEN FLOOR  
Scheduled Date/Time: 3/31/2023  
Completed Date/Time: 3/31/2023  
Inspector: Brad Sutton  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 3/29/2023 9:19 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: ROUGH IN  
Scheduled Date/Time: 6/13/2023  
Completed Date/Time: 6/13/2023  
Inspector: John B Kokoszka  
Result: DISAPPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 6/11/2023 4:12 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Plans call for 4 sc has 3sc front left room Missing 5 sc right rear at window Need floor truss layout and drawings Need 100 psi on test Need drawings for roof



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: ROUGH IN REINSPECT  
Scheduled Date/Time: 6/16/2023  
Completed Date/Time: 6/16/2023  
Inspector: John B Kokoszka  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 6/14/2023 5:29 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: T-POLE  
Scheduled Date/Time: 6/20/2023  
Completed Date/Time: 6/20/2023  
Inspector: John B Kokoszka  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 6/19/2023 8:34 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: INSULATION  
Scheduled Date/Time: 7/18/2023  
Completed Date/Time: 7/18/2023  
Inspector: Justin Ryan McLeod  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 7/16/2023 10:21 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: ENVIR OPERATIONS PERMIT  
Scheduled Date/Time: 9/27/2023  
Completed Date/Time: 9/28/2023  
Inspector: James Manhart  
Result: APPROVED  
Remarks:  
Notes:

Inspection Type: ENVIR WELL FINAL  
Scheduled Date/Time: 1/30/2024  
Completed Date/Time: 1/30/2024  
Inspector: James Manhart  
Result: APPROVED  
Remarks:  
Notes:

Inspection Type: TEMP POWER CERTIFICATION  
Scheduled Date/Time: 5/14/2024  
Completed Date/Time: 5/14/2024  
Inspector: Daniel L Floyd  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 5/11/2024 7:28 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: SEWER CONNECTION  
Scheduled Date/Time: 5/14/2024  
Completed Date/Time: 5/14/2024  
Inspector: Daniel L Floyd  
Result: CANCELLED  
Remarks: eTRAKiT Inspection Request  
Notes: 5/11/2024 7:33 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Needs to be uncovered



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: WATER CONNECTION  
Scheduled Date/Time: 5/14/2024  
Completed Date/Time: 5/14/2024  
Inspector: Daniel L Floyd  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 5/11/2024 7:33 PM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: SEWER CONNECTION  
Scheduled Date/Time: 7/9/2024  
Completed Date/Time: 7/9/2024  
Inspector: Daniel L Floyd  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 7/8/2024 8:23 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com

Inspection Type: FINAL SFD CRAWL\*\*  
Scheduled Date/Time: 8/29/2024  
Completed Date/Time: 8/29/2024  
Inspector: Daniel L Floyd  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 8/27/2024 8:43 AM Luis Enrique Vaca Sánchez

Contact Name: Luis Enrique Vaca Sánchez  
Site Address: 68 ROBINSON LN  
Phone: 9195217878  
e-Mail: Luis09980@gmail.com